

1 6/2/26
ARMJ-0142

STATE OF NEW JERSEY
DEPARTMENT OF LAW AND PUBLIC SAFETY
DIVISION OF STATE POLICE
BREATH TESTING INSTRUMENTATION SERVICE REPORT

1. Department: Toms River Township Police Department 255 Oak Ave Toms River, NJ 08753		2. Contact: Lt. Sermarini	4. Date: 06/02/2026
		3. Phone Number: 732-349-0150	5. County: Ocean
6. Alcotest Instrument Serial Number: ARMJ-0142	7. Simulator Component Serial Number: N/A	8. Temperature Probe Component Serial Number: N/A	

9. Reason for Service:
The Alcotest instrument was returned from outside evaluation and placed back in service.

10. Comments:
See Draeger Return and Repair form.

Last Known Sequential File #: N/A

- 11. The above Instrument/Component has been found to be in satisfactory working condition; no further action required.
- 12. The above Instrument/Component is placed out of service pending further evaluation.
- 13. The above Instrument/Component is placed back in service.

"I have been certified by the Attorney General as a Breath Test Coordinator/Instructor pursuant to N.J.A.C. 13:51, et. seq. In my official capacity as a Breath Test Coordinator/Instructor I perform inspections of evidential breath test devices and related components of evidential breath test systems. I have inspected the evidential breath test device listed on this report in my official capacity. The results of my inspection are recorded on this form. I certify that the forgoing statements made by me are true and accurate to the best of my knowledge. I am aware that if any of the forgoing statements made by me are willingly false, I am subject to punishment."

Tpr. II David Bellay #8112
Name & Badge Number (Print)

David Bellay #8112
Signature

06/02/2026
Date

STATE OF NEW JERSEY
DEPARTMENT OF LAW AND PUBLIC SAFETY
DIVISION OF STATE POLICE
BREATH TESTING INSTRUMENTATION SERVICE REPORT

1. Department: Toms River Township Police Department 255 Oak Ave Toms River, NJ 08753		2. Contact: Chris Fluck	4. Date: 02/17/2026
		3. Phone Number: 732-349-0150 x1104	5. County: Ocean
6. Alcotest Instrument Serial Number: ARMJ-0142	7. Simulator Component Serial Number: N/A	8. Temperature Probe Component Serial Number: N/A	

9. Reason for Service:
The Alcotest 9510 display is frozen on "SELF CHECK".

10. Comments:
On February 17, 2026 I responded to Toms River Township Police Department in reference to the Alcotest 9510 (Serial number ARMJ-0142) in reference to complaints of the Alcotest display being frozen on "SELF CHECK". Attempts to resolve the issue were unsuccessful. The data on the Alcotest was unable to be downloaded.

The instrument was placed out of service at this time and returned to Draeger Inc. for evaluation.

Last Known Sequential File #: 00724

11. The above Instrument/Component has been found to be in satisfactory working condition; no further action required.

12. The above Instrument/Component is placed out of service pending further evaluation.

13. The above Instrument/Component is placed back in service.

"I have been certified by the Attorney General as a Breath Test Coordinator/Instructor pursuant to N.J.A.C. 13:51, et. seq. In my official capacity as a Breath Test Coordinator/Instructor I perform inspections of evidential breath test devices and related components of evidential breath test systems. I have inspected the evidential breath test device listed on this report in my official capacity. The results of my inspection are recorded on this form. I certify that the forgoing statements made by me are true and accurate to the best of my knowledge. I am aware that if any of the forgoing statements made by me are willingly false, I am subject to punishment."

Tpr. II David Bellay # 8112
Name & Badge Number (Print)

David Bellay #8112
Signature

02/17/2026
Date

RETURN AND REPAIR FORM



Customer Information

B:

S:

Company Name: TOWNSHIP OF TOMS RIVER POLICE DEPARTMENT

Date Received: 03/05/2026

Date given to service: 04/07/2026

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: ARMJ-0142

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
4414160	A9510 Calibration	1 EA	
4414166	Labor	1.5 HR	
6808455	EC Sensor	1 EA	
6808374	Geared Engine	1 Ea	

Repair Notes: Device Stuck on "Self Check". Device reimaged and software reinstalled. Geared engine replaced. Replaced EC sensor due to Int-T value and EC values out of tolerance.

EC SENSOR = ARUL-0480
CAL W/QC AND OPS CHECK

Service Technician LM

Date: 04/07/2026

Delivery receipt



Customer no.
150059761

Number of report
311917671
Please reference on inquiries

Date of receiving Delivery receipt date
04.03.2026 08.04.2026

Consignee, 150059763
TOWNSHIP OF TOMS RIVER POLICE DEPAR
255 OAK AVE
TOMS RIVER NJ 08753-3383
USA

Customer, 150059761
TOWNSHIP OF TOMS RIVER
255 OAK AVE
TOMS RIVER NJ 08753-0876
USA

Your order

Date of order:
18.02.2026
Purch.ord.no.:
XC CONTRACT

Branch text

Draeger contact person

CONTRACT OPERATIONS
1-800-437-2437
Contract.operations@draeger.com

Page 1

Quantity	Description	Part no.	Equipment - No.	Serial - No.
000	Alcotest 9510 New Jersey	8327998	1028389729	ARMJ-0142
	CA/US* REPAIR ALCOTEST 9510 10 YR EXT WA			

Draeger Inc.
Our Tax ID: 23-1699096
3135 Quarry Road, Telford, PA 18969
An Equal Opportunity Employer M/F/V/H
Telephone 800-437-2437
<http://www.draeger.com>

Remit to:
LOCKBOX (Standard USPS)
Draeger, Inc.
PO Box 13369
Newark, New Jersey
07101-3362

Remit to:
LOCKBOX (Overnight)
FIS - Lockbox Operations
Attn: Draeger, Inc., Lockbox #13369
101 Woodcrest Road
Suite 201
Cherry Hill, New Jersey 08003

Remit US Wire Transfers to:
Account Name: Draeger Inc.
Account Number: 00-494-936
Transit Routing: 021001033
SWIFT: BKTRUS33
Deutsche Bank Trust Company Americas
60 Wall Street 25th Fl, New York, NY 10005

Service note

Customer no. 150059761 Number of report 311917671 Date of receiving 04.03.2026
Please reference on inquiries

Customer
 TOWNSHIP OF TOMS RIVER
 255 OAK AVE
 TOMS RIVER NJ 08753-0876
 USA

Consignee
 TOWNSHIP OF TOMS RIVER POLICE DEPAI
 255 OAK AVE
 TOMS RIVER NJ 08753-3383
 USA

Your order

Date of order: 18.02.2026
 Your reference: XC CONTRACT

NL-Text

Your contact person

CONTRACT OPERATIONS
 1-800-437-2437
 Contract.operations@draeger.com

Page 1

Item	Quantity	Part no. Description
		<p>Service Order: 155263421</p> <p>Device Stuck on "Self Check". Device rei Eq.No. : 1028389729 SN: ARMJ-0142 Material: 8327998 Alcotest 9510 New Jersey Inv.No. : Location: Device Stuck on "Self Check". Device reimaged and software reinstalled. Geared engine replaced. Replace EC sensor due to Int-T value and EC values out of tolerance. Calibration needed.</p> <p>Awaiting Part - EC Sensor 3/27</p> <p>REPAIR ALCOTEST 9510 10 YR EXT WARRANTY</p>
	0,0 H	



Service Report

Customer No. 0150059763	Contract 317024077	Dispatch No.: U08124375	Date 04/08/2026
-----------------------------------	------------------------------	-----------------------------------	---------------------------

Responsible Service Engineer Lyfon Morris (5489)
--

Postal Address
TOWNSHIP OF TOMS RIVER POLICE DEPARTMENT

Page 1 / 1

255 OAK AVE
TOMS RIVER, NJ08753-3383
CHRISFLUCK

Sold To Party 0150059761 TOWNSHIP OF TOMS RIVER
--

255 OAK AVE
TOMS RIVER, NJ08753-0876

Your order dated 03/06/2026 XC CONTRACT
--

Your contact person CHRIS FLUCK 732-349-0150 x1104 732-349-0150 x1104

Pos.	Quant.	Part No.	Description	EQ. No. / UDI
		8327998	Alcotest 9510 New Jersey Serial No.: ARMJ-0142 S/O 155263421 Return Authorization: 311917671 Inv.No.: Location: Work performed: Device Stuck on "Self Check". Device reimaged and software reinstalled. Geared engine replaced. Replaced EC sensor due to Int-T value and EC values out of tolerance. New EC sensor (ARUL-0480) installed. Calibration complete.	1028389729 /
010	1.00 items	6808374	Geared Engine, A7110/A9510	
020	1.00 items	6808455	Sensor Alcotest B	
030	1.50 Hour	R004	Repair Time - Workshop	